

Message

From: NSK Env Coord Air Quality & Spill Plans [n1037@conocophillips.com]
Sent: 7/3/2019 9:07:13 PM
To: Pavitt, John [Pavitt.John@epa.gov]
CC: Williams, Christopher [Williams.Christopher@epa.gov]; Olds, Jason R (DEC) [jason.olds@alaska.gov]; Perry, Laura K [Laura.Perry@conocophillips.com]
Subject: RE: [EXTERNAL]EPA/ADEC air compliance inspection, CPF#1

[Resending without attachment, since the first email bounced back as undeliverable]

John,

Thank you for the call and email yesterday. I have confirmed with the facility that nothing is scheduled for July 18th that would prevent you from accessing the area.

When you arrive, you can check in at our office in KOC. We are in Room 130.

What time do you anticipate arriving? I have arranged to have an operator accompany the group to conduct the necessary air monitoring, so you will not need to get hot work permits for each location.

Please let us know if you need anything else prior to the inspection.
Thank You,

Catie Coursen / Brad Broker
North Slope Environmental Coordinator
Air Quality and Spills Plans
Office: 907.659.7242
Mobile: 907.943.1545 Pager: 669
E-mail: n1037@conocophillips.com

From: Pavitt, John <Pavitt.John@epa.gov>
Sent: Tuesday, July 2, 2019 12:38 PM
To: n1037@conocophillips.com
Cc: Williams, Christopher <Williams.Christopher@epa.gov>; Olds, Jason R (DEC) <jason.olds@alaska.gov>
Subject: [EXTERNAL]EPA/ADEC air compliance inspection, CPF#1

[Resending w/ corrected email address]

Catie Coursen and Brad Broker
Environmental Coordinator
ConocoPhillips, CPF #1

Catie, I'm sending this email to follow up on my phone call today. I called to let you know the Environmental Protection Agency (EPA) and Alaska Department of Environmental Conservation (ADEC) are planning a joint air compliance inspection at the CPF #1 facility in Prudhoe Bay, AK on Thursday, July 18.

The inspection will focus on compliance with New Source Performance Standards (NSPS), Subparts OOOO and OOOOa – Standards of Performance for Crude Oil and Natural Gas Facilities, under the Clean Air Act.

During the inspection, the inspectors will need access to areas subject to the rules, including well affected facilities and collections of fugitive emissions components. We will be taking photographs and videos with a digital camera and an optical gas imaging (OGI) camera, in addition to, measuring concentrations of VOC with a photo-ionization detector (PID). A hot work permit may be required from you to access these areas. Please confirm where we should check-in with you at the start of the inspection.

Thank you for your assistance in helping to coordinate this on-site inspection. Please let me know if you have any questions about this email or the inspection schedule.

Sincerely,

John Pavitt, Air Compliance Inspector
Air and Toxics Enforcement Section
U.S. EPA Region 10
Alaska Operations Office
Anchorage, AK
Phone: (907) 271-3688